

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 31-7-2023

Geophysical Borehole Logging Report By

Sh. R. Chandra, Sr. Scientist (Retd.),

The geo-electric logging was done in the borehole at village BalBhariya, Block Pachperwa, District Balrampur, U.P.

Name of Village : BalBhariya (82°42'21.6"E, 27°34'06.5"N)

Block : Pachperwa

District : Balrampur

Date : 31-7-2023

Depth logged : 269.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	10	4	fine sand
2	10	24	14	Clay with Kankar
3	24	30	6	fine sand
4	30	34	4	Clay with Kankar
5	34	39	5	fine sand
6	39	68	29	Clay with Kankar
7	68	74	6	fine sand
7	74	100	26	Clay with Kankar
8	100	112	12	fine sand
9	124	140	16	Clay with Kankar
10	140	148	8	fine sand
11	148	170	22	Clay with Kankar
12	170	174	4	fine sand
13	174	198	24	Clay with Kankar
14	198	204	6	fine sand
15	204	208	4	Clay with Kankar
16	208	210	2	fine sand
17	210	218	8	Clay with Kankar
18	218	226	8	fine sand
19	226	253	27	Clay with Kankar
20	253	256	3	fine sand
21	256	269	13	Clay with Kankar

For First Best Solution

Authorized Signatory

For First Best Solution

Naray

Proprietor