

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:24-1-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Baksaria, Block Utraula, District Balrampur, U.P.

Name of Village : Baksaria (82° 25'53.4" E,27° 18'04"N)

Block – Utraula

District: Balrampur

Date : 24-1-2024

Depth logged : 165.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	5	23	18	fine sand
2	23	27	4	Clay with kankar
3	27	40	13	fine sand
4	40	45	5	Clay with kankar
5	45	75	30	fine sand
6	75	80	5	Clay with kankar
7	80	94	14	fine sand
8	94	105	11	Clay with kankar
9	105	110	5	fine sand
10	110	116	6	Clay with kankar
11	116	135	19	fine sand
12	135	142	7	Sandy Clay
13	142	165	23	fine sand

For First Best Solution

Authorized Signatory

For First Best Solution
Niraj
Proprietor