

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 1-8-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Rampur Grant, Block Rehra Bazar, District Balrampur, U.P.

Name of Village : Rampur Grant, (82° 23'28.1"E, 27°09'30.04"N)

Block – Rehra Bazar

District: Balrampur

Date: 1-8-2023

Depth logged : 164.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	34	28	medium to fine sand
2	34	38	4	Clay with kankar
3	38	99	61	medium to fine sand
4	99	112	13	Clay with kanar
5	112	118	6	fine sand
6	118	124	6	Clay with kankar
7	124	130	6	fine sand
8	130	138	8	Clay with kankar
9	138	162	24	fine sand
10	162	164	2	Clay with kankar

For First Best Solution

Authorized Signatory
For First Best Solution

Niraj

Proprietor