

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:10-11-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Katara, Block Utraula, District Balrampur, U.P.

Name of Village : Katara

Block – Utraula

District: Balrampur

Date : 10-11-2023

Depth logged : 165.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thicknes s (m)	LITHOLOGY
	From	To		
1	6	40	34	fine sand
2	40	49	9	Clay and kankar
3	49	62	13	fine sand
4	62	65	3	Clay and kankar
5	65	74	9	fine sand
6	74	76	2	Clay and kankar
7	76	83	7	fine sand
8	83	85	2	Clay with Kankar
9	85	88	3	fine sand
10	88	90	2	Clay and kankar
11	90	94	4	fine sand
12	94	96	2	Clay with Kankar
13	96	98	2	fine sand
14	98	120	22	Clay with Kankar
15	120	140	20	fine sand
16	140	143	3	Clay with Kankar
17	143	146	3	fine sand
18	146	148	2	Clay with Kankar
19	148	165	17	fine sand

For First Best Solution

Authorized Signatory

For First Best Solution

Proprietor