



Medini

GSTIN : 09BDGPB5432F12V

Shri Medini

E-11, South City, Raebarell Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 12-02(ii)/JJM/Logging/2022-23

Dated : 12-02-2023

GEOPHYSICAL WELL LOGGING REPORT

Village : Badagaon
Block : Sangrampur
District : Amethi
Date of Logging : Feb. 12, 2023
Logged Depth : 170 mbgl.
Borehole Drilled By : Vindhya Telelinks – Gaja Engineering PVT. Ltd. (J.V.)
Drilled Depth : 175 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	17	22	05	Good
2	25	30	05	Good
3	52	57	05	Good
4	60	64	04	

Note :-

Above mentioned E.Logs/parameters reveals:-

- Above mentioned groups contains fine sediments.
- Zone at S.Nos. 1 & 2 mixed with Kanker.
- Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.
- Below 101 mts. till logged depth borehole contain deteriorated/saline quality of formation water.

For Shri Medini


(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.

Verified as per logs provided



*G.Sh
13/02/23*