

Ref 606 -D / AX - 2023 Date 06.06.2023

Geophysical Borehole Logging Report

Name of the site : Daudpur Kurmi, Block - Sathiyaoon
District : Azamgarh
Date : 06.06.2023
Depth logged : 206.0 mbgl
Depth drilled : 210.0 mbgl - as reported
Logger used : Robertson make
Presence : Representative of M/S Sudhakara Infratech Pvt. Ltd., Azamgarh
Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water;

Sl.No.	Depth range(mbgl)	Thickness(m)	Remarks
1	30.0--37.0	7.0	Good all
2	47.0--62.0	15.0	
3	76.0--80.0	4.0	
4	83.0--90.0	7.0	
5	146.0--158.0	12.0	
6	175.0--179.0	4.0	
7	188.0--195.0	7.0	

Note. All zones are intermixed with kankar. Quality of the formation water is deteriorating marginal to saline in between 94.0 to 130.0 mbgl.



for Aqua Xplore

CC;

M/S Sudhakara Infratech Pvt. Ltd., Azamgarh