

# GROUND WATER SURVEY CONSULTANCY GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL ELECTOLOGGING REPORT

A-291

Ref No:- P- 160

Date:- 18-04-2023

### NAME OF SITE

GRAM PANCHAYAT- Satha Nabipur

BLOCK- Jalesar

DISTT- Etah

### NAME OF AGENCY

M/s ION Exchange India Limited  
Etah



## GROUND WATER SURVEY CONSULTANCY


Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.

112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M) : 9412260823, 9794625420, 9761163000, Email : gwsc\_agra@yahoo.com

**ISO ; 9001 : 2015**

Ground Water Survey Consultancy  
Agra



# REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- SATHA NABIPUR, BLOCK- JALESAR, DISTT-ETAH  
UNDER  
JAL JIVAN MISSION

## Introduction :

A Deep bore hole was drilled 103 mtrs. depth. and Logged depth 97 mtrs. at above site. Was drilled by M/s ION Exchange India Limited, Etah.

On the request of M/s ION Exchange India Limited, Etah. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 18.April.2023

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major Aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

Mud Resistivity = 12.56 Ohms.

Drilling Water Resistivity = 13.82 Ohms.

Approx Water Level = 20 Mtr.

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 8	3	Clay	
3.	8 - 15	7	Fine sand	
4.	15 - 20	5	Clay kankar	
5.	20 - 33	13	Medium sand & kankar	Med. To Marginally
6.	33 - 36	3	Clay kankar	
7.	36 - 42	6	Medium sand	Med. To Marginally
8.	42 - 45	3	Clay kankar	
9.	45 - 50	5	Fine sand	Med. To Marginally
10.	50 - 53	3	Clay kankar	
11.	53 - 60*	7	Medium sand	Med. To Marginally
12.	60 - 67	7	Clay kankar	
13.	67 - 80	13	Fine to Medium sand	Saline
14.	80 - 97	17	Clay kankar	

Ground Water Survey Consultancy



**Conclusions and Recommendations :-**

1. The Lithology broadly tallies with that of drill cutting strata chart.
2. The zones marked with asterisk (\*) appear to be aquifer zones for possible Development of tube well.
3. The Quality of water is expected Medium to Marginally Saline.
4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

**Geophysicist**



**Ground Water Survey Consultancy**




Rno a  
 N16 (SN)  
 N64 (LN)  
 LAT

Location:  
 Project: Agra  
 Date: 14-02-2013  
 Time: 12:13  
 Operator:  
 No. Cont:

System No:  
 IGS/201/10-11

SP  
 DMAPL-2  
 Ground Water  
 Survey  
 Consultancy  
 - AGRA INDIA



# REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- SATHA NABIPUR, BLOCK- JALESAR, DISTT-ETAH  
UNDER  
JAL JIVAN MISSION

## Introduction :

A Deep bore hole was drilled 103 mtrs. depth. and Logged depth ~~97~~ mtrs. at above site. Was drilled by M/s ION Exchange India Limited, Etah.

On the request of M/s ION Exchange India Limited, Etah. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 18.April.2023

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major Aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

Mud Resistivity = 12.56 Ohms.

Drilling Water Resistivity = 13.82 Ohms.

Approx Water Level = 20 Mtr.

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 8	3	Clay	
3.	8 - 15	7	Fine sand	
4.	15 - 20	5	Clay kankar	
5.	20 - 33	13	Medium sand & kankar	Med. To Marginally
6.	33 - 36	3	Clay kankar	
<del>7.</del>	36 - 42	6	Medium sand	Med. To Marginally
8.	42 - 45	3	Clay kankar	
<del>9.</del>	45 - 50	5	Fine sand	Med. To Marginally
10.	50 - 53	3	Clay kankar	
<del>11.</del>	53 - 60*	7	Medium sand	Med. To Marginally
12.	60 - 67	7	Clay kankar	
13.	67 - 80	13	Fine to Medium sand	Saline
14.	80 - 97	17	Clay kankar	

G.Sh  
19/04/23

Ground Water Survey Consultancy



- Logging performed as per SWSSM guidelines.  
- Ground water quality interpreted by form as per their logger calibration