

GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No:- 335

Date:- 19-01-2022

NAME OF SITE

Gram Panchayat- Painpal BLOCK- Wazirganj DISTT- Badaun


NAME OF AGENCY

M/s PNC-SPML-JV
Badaun



GROUND WATER SURVEY CONSULTANCY
Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M) : 9412260823, 9794625420, 9761163000, Email : gwsc_agra@yahoo.com

ISO : 9001 : 2015



REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- PAINPAL, BLOCK- WAZIRGANJ, DISTT.- BADAUN
UNDER
JAL JIVAN MISSION

Introduction :

A Deep bore hole was drilled 140 mtrs. depth, and Logged depth 131 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun, a Geophysical well Logging is conduct at above bore hole using IGIS Well Logger on 19.Jan.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 18	13	Dry sand	
3.	18 - 25	7	Clay kankar	
4.	25 - 40	15	Fine sand	Good
5.	40 - 45	5	Clay kankar	
6.	45 - 61*	16	Medium sand & Kankar	Good
7.	61 - 65	4	Clay kankar	
8.	65 - 90*	25	Medium sand	Good
9.	90 - 105	15	Clay kankar	
10.	105 - 125*	20	Fine to Medium sand	Good
11.	125 - 131	6	Clay kankar	



Conclusions and Recommendations :-

1. The Lithology broadly tallies with that of drill cutting starta chart.
2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
3. The Quality of water is expected Good.
4. Expected discharge is 1000 to 1200 L.P.M.
5. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations

Geophysicist



Ground Water Survey Consultancy



Fig. 2

NITIS ISN
ASCE LN
LAT

Topographic profile
Bore No. 10
Date 20/01/2016
Location
Bhagwati
Extn.
Dhankot, Gurgaon

Cham m

