Auth ri ed Signatory

## GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

### GEO-PHYSICAL WELL ELECTOLOGGING REPORT

RefNo:- 453

Date. 17-02-2022

#### NAME OF SITE

Gram Panchayat- Noor Nagar Kauria

**BLOCK-** Asafpur

**DISTT-Badaun** 

NAME OF AGENCY

M/s PNC-SPML-JV Badaun



#### **GROUND WATER SURVEY CONSULTANCY**

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112

A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

Ground W urvey Itancy
Agra

#### Agra

# REPORT ON GEOPHYSICAL WELL LOGGING AT

# GRAM PANCHAYAT- NOOR NAGAR KAURIA, BLOCK- ASAFPUR, DISTT.- BADAUN UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 110 mtrs. depth. and Logged depth 110 mtrs. at above site. was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JVJ Badaun. a Geophysical well Logging is conduct at above bore hole using IGIS Well Logger on 17.Feb.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral.

Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

| S.N0. | Defth range(m) | Thickness(m) | Lithology           | Expected Water Quality |
|-------|----------------|--------------|---------------------|------------------------|
| 1.    | 5              | 5            | Surface soil        |                        |
| 2.    | 18             | 13           | Dry sand            |                        |
| 3.    | 18 - 33        | 15           | Clay                |                        |
| 4.    | 33 - 50*       | 17           | Medium sand         | Good                   |
| 5.    | 50 - 58        | 8            | Clay kankar         |                        |
| 6.    | 58 - 62        | 4            | Fine sand           | Good                   |
| 7.    | 62 - 65        | 3            | Clay kankar         |                        |
| 8.    | 65 —           | 23           | Medium sand         | Good                   |
| 9.    | 88 94          | 6            | Clay kankar         |                        |
| 10.   | 94 — 100*      | 6            | Fine to Medium sand | Good                   |
| 11.   | 100 - 105      | 5            | Cla kankar          |                        |
| 12.   | 105 - 110      | 5            | Fine sand           | Good                   |



#### Conclusions and Recommendations:-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. Expected discharge is 1000 to 1100 L.P.M.
- 5. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water ter sally Colonsultancy

