## REPORT ON GEOPHYSICAL WELL LOGGING

## GRAM PANCHAYAT- ALLIPUR CHACHIPUR, BLOCK- ISLAMNAGAR DISTT.- BADAUN UNDER JAL JIVAN MISSION

## Introduction :

A Deep bore hole was drilled 112 mtrs. depth. and Logged depth 110 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun. a Geophysical well Logging is conduct at above bore hole using IGIS Well Logger on 17.Sep.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected Water Ouality
1.	0 - 5	5	Surface soil	
2.	5 - 16	11	Dry sand	
3.	16 - 26	10	Sandy clay	
4.	26 - 35	9 .	Fine sand	Good
5.	35 - 44	9	Clay kankar	
6.	44 - 51*	7	Medium sand	Good
7.	51 - 65	14	Clay kankar	
8.	65 - 84*	19	Medium sand	Good
9.	84 - 87	3	Kankar	
10.	87 - 92*	5	Medium sand	Good
11.	92 - 103	11	Clay kankar	
12.	103 - 110	7	Sandy clay	



## Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible Development of tube well.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist Ground Water Survey Consultancy

Agna \* Journal Survey



• ••• ~