# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:- 180

Date: - 03-05-2022

#### NAME OF SITE

Gram Panchayat- Firozpur

BLOCK-Bisauli

DISTT-Badaun

NAME OF AGENCY

M/s PNC-SPML-JV Badaun



## GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO; 9001: 2015

Ground Water-Survey Consultancy

# REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- FIROZPUR, BLOCK- BISAULI, DISTT.- BADAUN
UNDER
JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 112 mtrs. depth. and Logged depth 109 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun. a Geophysical well Logging is conduct at above bore hole using IGIS Well Logger on 03.May.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 15	10	Dry sand	
3.	15 - 31	16	Clay kankar	
4.	31 - 53	22	Medium sand	Good
5.	53 - 62	9	Clay kankar	
6.	62 - 76*	14	Medium sand	Good
7.	76 - 84	8	Clay kankar	
8.	84 - 96*	12	Medium sand	Good
9.	96 - 105	9	Clay kankar	
10.	105 - 109	1	Sandy clay	



### Conclusions and Recommendations :-

- The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (\*) appear to be aquifer zones for possible Development of tube well.
- The Quality of water is expected Good.
- 4. Expected discharge is 700 to 900 L.P.M.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

**Ground Water Survey Consultancy** 

Table Street, and a street, an 0 Rho a N16 (SN, NEGLIN) SP (m V) . 0hm m m V 5 5 H 18--62 89 8-3 150-189-5 8 5 5 ö 0-5-2-20 2-8-3-Mary Mary Works 6-5-8-3 Depth (m) 8-8-3-75 8-8-8-95-8-<u>g</u>-

