

# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-2081

Date:- 01-11-2023

### NAME OF SITE

GRAM PANCHAYAT- Afjalpur

BLOCK- Kasganj

DISTT- Kasganj

### NAME OF AGENCY

M/s PNC-SPML-JV  
Kasganj



## GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.

112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M) : 9412260823, 9794625420, 9761163000, Email : gwsc\_agra@yahoo.com

**ISO ; 9001 : 2015**

Ground Water Survey Consultancy



# REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- AFJALPUR, BLOCK- KASGANJ, DISTT- KASGANJ  
UNDER  
JAL JIVAN MISSION

## Introduction :

A Deep bore hole was drilled 100 mtrs. depth. and Logged depth 100 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Kasganj.

On the request of M/S PNC-SPML-JV, Kasganj. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 01.Nov.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

Mud Resistivity = 15.19 Ohms.

Drilling Water Resistivity = 16.33 Ohms.

Approx Water Level = 18 Mtr.

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5	Clay kankar	
3.	10 - 16	6	Medium sand	
4.	16 - 19	3	Clay kankar	
5.	19 - 21	2	Fine sand	Medium
6.	21 - 28	7	Clay kankar	
7.	28 - 32	4	Medium sand	Medium
8.	32 - 35	3	Clay kankar	
9.	35 - 40*	5	Medium sand	Medium
10.	40 - 60	20	Clay kankar	
11.	60 - 79*	19	Medium sand & kankar	Medium
12.	79 - 88	9	Clay kankar	
13.	88 - 93*	5	Medium sand	Medium
14.	93 - 100	7	Clay kankar	

Ground Water Survey Consultancy



**Conclusions and Recommendations :-**

1. The Lithology broadly tallies with that of drill cutting strata chart..
2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
3. The Quality of water is expected Medium.
4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

**Geophysicist**



**Ground Water Survey Consultancy**

No. 1  
 N16 (SN)  
 NS4(LN)  
 LAT

Logging Details:  
 depth: 100 m  
 date: 21/02/2023  
 time: 11:30  
 location: Agia India

Logger's No:  
 IGSS/03/21-22

DIAPL-2  
 Logger Connected by  
 GROUND WATER SURVEY CONSULTANCY - AGIA INDIA

