(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 Date: 9-12-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Itrauar, Block Manakpur, District Gonda, U.P.

Name of Village: Itrauar (82º 09'59.4"E,27º03'15.3"N)

Block - Manakpur District: Gonda

Date

: 9-12-2023

Depth logged: 164.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	28	22	Fine to medium Sand
2	28	35	7	Clay and kankar
3	35	40	5	Fine sand
4	40	52	12	sandy clay
5	52	62	10	Fine sand
6	62	67	5	Clay and kankar
7	67	71	4	Fine sand
8	71	73	2	sandy clay
9	73	79	6	Fine sand
10	79	81	2	sandy clay
11	81	83	2	Fine sand
12	83	85	2	sandy clay
13	85	92	7	Fine sand
14	92	96	4	sandy clay
15	96	103	7	Fine sand
16	103	105	2	sandy clay
17	105	110	5	Fine sand
18	110	118	8	Clay and kankar
19	118	126	8	Fine sand



S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
20	126	130	4	sandy clay
21	130	140	10	Fine sand
22	140	143	3	sandy clay
23	143	164	21	Fine sand



For First Best Solution

Authorized Signatory

Viraj

Proprietor