(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 5-3-2024

## **Geophysical Borehole Logging Report** By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Palhadpur, Block Colonelgani, District Gonda, U.P.

Name of Village: Palhadpur

Block: Colonelgani District: Gonda

: 5-3-2024

Depth logged: 330.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	18	12	Fine Sand
2	18	21	3	Clay and kankar
3	21	30	9	Fine sand
4	30	37	7	Clay and kankar
5	37	56	19	Fine sand
6	56	63	7	sandy Clay
7	63	110	47	Fine sand
8	110	116	6	Clay and kankar
9	116	145	29	Fine sand
10	145	151	6	sandy Clay
11	151	160	9	Fine sand
12	160	164	4	sandy Clay
13	164	170	6	Fine sand
14	170	205	35	Clay and kankar
15	205	220	15	Fine sand
16	220	235	15	Clay and kankar
17	235	244	9	Fine sand
18	244	250	6	Clay and kankar



S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		LEUNY STIMMENT
19	250	273	23	Fine sand
20	273	275	2	Clay and kankar
21	275	279	4	Fine sand
22	279	299	20	Clay and kankar
23	299	309	10	Fine sand
24	309	330	21	sandy Clay

**For First Best Solution** Authorized Signatory

For First Best Solution