GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-B- 1642

Date:- 02-09-2023

NAME OF SITE

GRAM PANCHAYAT- Changeeri

BLOCK-Dhanipur

DISTT- Aligarh

NAME OF AGENCY

M/s Kalpataru Power Transmission Limited
Aligarh



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.

112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- CHANGEERI, BLOCK- DHANIPUR, DISTT- ALIGARH UNDER
JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 110 mtrs. depth. and Logged depth 96 mtrs. at above site. Was drilled by M/s Kalpataru Power Transmission limited, Aligarh.

On the request of M/s Kalpataru Power Transmission limited, Aligarh. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 02.Sep.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major Aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

Mud Resistivity = 15.27 Ohms.

Drilling Water Resistivity = 16.40 Ohms.

Approx Water Level = 6 Mtr.

| S.No. | Depth range(m) | Thickness(m) | Lithology | Expected Water |
|-------|----------------|--------------|------------------------|------------------|
| 1. | 0 - 5 | 5 | Surface soil | Quality |
| 2. | 5 - 10 | 5 | Clay kankar | |
| 3. | 10 - 33 | 23 | Fine to Med sand & kan | Medium |
| 4. | 33 - 40 | 7. | Clay kankar | wiedium |
| 5. | 40 - 47* | 7 | Medium sand | Medium |
| 6. | 47 - 54 | 7 | Clay kankar | tyteatum |
| 7. | 54 - 58 | 4 | Kankar | |
| 8. | 58 - 65 | 7 | Clay kankar | |
| 9. | 65 - 72* | 7 | Fine to Medium sand | Medium Medium |
| 10. | 72 - 84 | 12 | Clay kankar | |
| 11. | 84 - 90* | 6 | Medium sand | |
| 12. | 90 - 96 | 6 | Clay kankar | |

Note: - Please ensure pre-monsoon water level before lower the well assembly

Ground Water Survey Consultancy

Conclusions and Recommendations :-

- The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible Development of tube well.
- The Quality of water is expected Medium.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy



