FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Mob: - 8744928231

Date:30-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Trilokpur, Block Hariharpur Rani, District Shravasti, U.P.

Name of Village : Akbarpur (81°56'33.8"E27°38'08.6"N)

Block – Hariharpur Rani

District: Shravasti

Date : 30-10-2023 Depth logged : 166.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	То			
1	6	25	19	fine sand	Good
2	25	30	5	Clay with kankar	
3	30	43	13	fine sand	Good
4	43	67	24	Clay with kankar	
5	67	80	13	fine sand	Good
6	80	86	6	Clay with kankar	
9	86	92	6	fine sand	Good
10	92	109	17	Clay with kankar	
11	109	160	51	fine to medium sand	Good
12	160	166	6	Clay with kankar	

For First Best Solution

Authorized Signatory

For First Best Solution

Proprietor