FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Mob: - 8744928231

Date:28-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Ramnagar Chairidih, Block Sirsiya, District Shrawasti, U.P.

Name of Village: Ramnagar Chairidih

Block – Sirsiya District: Shrawasti

Date : 28-10-2023 Depth logged : 165.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range		Thickness (m)	LITHOLOGY	Quality
	(m.bgl)				
	From	То			
1	6	10	4	Clay with kankar	Good
2	10	15	5	fine sand	
3	15	20	5	Clay with kankar	Good
4	20	27	7	fine sand	
5	27	45	18	Clay with kankar	
6	45	50	5	fine sand	Good
9	50	58	8	Clay with kankar	
10	58	61	3	fine sand	Good
11	61	65	4	Clay with kankar	
12	65	74	9	fine sand	Good
13	74	77	3	Clay with kankar	
14	77	85	8	fine sand	Good
15	85	92	7	Clay with kankar	
16	92	97	5	fine sand	Good
17	97	110	13	Clay with kankar	
18	110	117	7	fine sand	Good
19	117	120	3	Clay with kankar	
20	120	131	11	fine sand	Good
21	131	135	4	Clay with kankar	
22	135	150	15	fine sand	Good
23	150	165	15	Clay with kankar	

For First Best Solution

Authorized Signatory

For First Best Solution