

GSTIN:: 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,

Lucknow-226025

E-mail.: shri.medini@gmail.com Mob.: 9554412795, 8887691798

Ref. No.: 07-02(iii)/JJM/Logging/2022-23

Dated: 08-02-2023

GEOPHYSICAL WELL LOGGING REPORT

Village

: Bhausinghpur

Block

Sangrampur

District

: Amethi

Date of Logging

: Feb. 07, 2023

Logged Depth

163 mogl.

Borehole Drilled By Drilled Depth

170 meters (as reported)

Vindhya Telelinks - Gaja Engineering PVT. Ltd. (J.V.)

M

South City Lucknow

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered -

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To	12.52	8.8
1	24	31	07	Good
2	41	56	15	Good

Note :-

Above mentioned E.Logs/parameters revels:-

Above mentioned groups contains fine sediments.

Above mentioned groups contains fine sediments.

iii. Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.

Below 71 mts. till logged depth i.e. 163 mbgl. borehole contain deteriorated/saline quality of logs bround formation water.

For Shri Medini

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant

Retired from Irrigation Department (Mechanical)

Uttar Pradesh, LUCKNOW.