

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:18-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Dhannidih & Sarra bojhi-1, Block Sirsiya, District Shrawasti, U.P.

Name of Village : Dhannidih & Sarra bojhi-1

Block – Sirsiya

District: Shrawasti

Date : 18-10-2023

Depth logged : 167.0 mbgl

Logger use : Robertson

Presence: Rep. of M/S D.S.A.

Construction, Shrawasti

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
1	6	8	2	fine sand	Good
2	8	11	3	Clay with kankar	
3	11	14	3	fine sand	Good
4	14	44	30	Clay with kankar	
5	44	48	4	fine sand	Good
6	48	54	6	Clay with kankar	
9	54	57	3	fine sand	Good
10	57	61	4	Clay with kankar	
11	61	66	5	fine sand	Good
12	66	86	20	Clay with kankar	
13	86	90	4	fine sand	Good
14	90	100	10	Clay with kankar	
15	100	104	4	fine sand	Good
16	104	112	8	Clay with kankar	
17	112	114	2	fine sand	Good
18	114	116	2	Clay with kankar	
19	116	121	5	fine sand	Good
20	121	129	8	Clay with kankar	
21	129	134	5	fine sand	Good
22	134	142	8	Clay with kankar	

Handwritten signature

23	142	148	6	sandy clay	
24	148	156	8	Clay with kankar	
S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
25	156	158	2	fine sand	Good
26	158	162	4	Clay with kankar	
27	162	165	3	fine sand	Good
28	165	167	3	sandy clay	

JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA

Seenu


For First Best Solution
For First Best Solution

Niraj

Proprietor
Authorized Signatory

Seenu
Seenu