GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-2124

Date: - 05-11-2023

NAME OF SITE

GRAM PANCHAYAT- lakhamanpur Salarpur Zone-A DISTT- Bahraich BLOCK-Nawabganj

NAME OF AGENCY

Gyan Scientific Traders (India) Pvt. Ltd.
Bahraich



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy



REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- LAKHAMANPUR SALARUR ZONE-A, BLOCK- NAWABGANJ, DISTT- BAHRAICH

UNDER JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 220 mtrs. depth. and Logged depth 207 mtrs. at above site. Was drilled by M/s Gyan Scientific Traders (India) Pvt. Ltd., Bahraich.

On the request of M/s Gyan Scientific Traders (India) Pvt. Ltd., Bahraich. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 10.July.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major Aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

Mud Resistivity = 17.20 Ohms.

Drilling Water Resistivity = 19.20 Ohms.

Approx Water Level = 2 Mtr

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 15	10	Clay kankar	
3.	15 - 20	5	Medium sand	Good
4.	20 - 30	10	Clay kankar	
5	30 - 33	3	Fine sand	Good
6.	33 - 40	7	Clay kankar	This was the second
7.	40 - 50*	10	Medium sand	Good
8.	50 - 65	15	Clay kankar	
9.	65 - 71*	6	Medium sand	Good
10.	71 - 85	14	Clay kankar	
11.	85 - 110*	25	Medium sand & kankar	Good
12.	110 - 118	8	Clay kankar	
13.	118 - 125*	7	Medium sand	Good
14.	125 - 130	5	Clay kankar	
15.	130 - 140*	10	Medium sand	Good
16.	140 - 150	10	Clay kankar	
17.	150 - 155*	5	Medium sand	Good
18.	155 - 170	15	Clay kankar	
19.	170 - 175*	5	Medium sand	Good
20.	175 - 187	12	Clay kankar	
21.	187 - 195*	8	Fine to medium sand	Good
22.	195 - 207	12	Clay kankar	3,4

Ground Water Survey Consultancy

Conclusions and Recommendations:

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible Development of tube well.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy



