SHVARAV CHURON

(E&M U.P. JAL NIGAM RURAL MORADABAD)	(TPI)		VEPL
	MIS RIG CONSTRUCTION		VEB
	Coarse sand	114 M	109 M
	Medium Coarse sand	105 M	101 M
	Medium sand	98 M	96 M
	Medium Coarse sand	94.50	91.5 M
	Medium sand	90 M	86 M
	Coarse sand	82 M	78 M
	Coarse sand	68.50	59 M
	Medium sand	57 M	54 M
	LOGGING REPOET AS-	LOC	

	TIST OF TUBE	LIST OF TUBE WELL ASSEMBLY UNITS	JNITS
ON MS	DISCRIPTION	QTY. (M)	DIAMETER
-	PLAIN PIPES	12.00	200 mm
2	PLAIN PIPES	60.23	1.50 mm
Cu3	STOTTED PIPES	17.00	150 mm
110 (N)Z	MM DIA PLAIN PIPES	ES	42.00 M
200X150	MM DIA REDUCER		0.20 M
1.50 nun	MM DIA PLAIN PIPES	ES	60.23 M
tim 05.3	MM DIA SLOTTED PIPES	PIPES	17.00 M
		TOTAL DEPTH	119.43 M
		AGL	-0.50 M
	OT TVLOI.	TOTAL LOWERING DEPTH	118.93 M

ONLING DARK 024020	BLETVSIR A 10 III	10110	SCHEME STATE BRIDS NDA	CHAIN BO	ISTA NOR ARM	BURN BURN	I I M M I I I
21112023	REALINGE	103 VO 227 D FILASVIII 4017 2 ON VO 1	HASI NDA	A 15 GOT HE ISABLI OLD STANDARD	OUTLAND TO HAVE A HARVARISTA MOUNTAINS	WITHS MS II TO THE HELDS VIGILIS ATTIVATED BY	IT BE WELL ASSEMBLY CHARL

DRILLING & LOWERING

COVERA COVERA

	SLOTTED		SLOTTED			SLOTTED		SLOTTED		SLOTTED			SLOTTED	SLOTTED												
_	2	ယ	4	ப	6	7	8	9	10	=	12	ដ	14	15	16	17	8	19	/							
6,01	3,00	6.04	2 00	2.34	6.05	100	3.20	2 00	6.01	2 00	6.00	6.00	1.00	6.00	0.50	6.03	6.03	6.02	0.20	6.00	6.00	6.00	6.00	6.00	6.00	6.00
	AND RES		STATE OF		_	MACHO.]			1													Ч
118.93 N	112.92	109.92 M	103.88 M	101.88 M		93.49 M	92.49 M	89.29 M	87.29 M	81.28 M	79.28 M		67.28 M		60.28 M				41.70 M	41.50 M						

GSTIN. 03BNPPS2540N1ZK



M/S E.R. TECHNOLOGIES

(Govt. Contractor of PH & Civil Works & Electrical Works)

(Specialist in: Deep Tube well, Sick Tube well, Geological and Hydro-Geological Survey, Electric Logging of Borehole, Videography of Borehole, Water Sample & Soil Testing etc.

	1/10/2023
Ref	Dated

REPORT OF ELECTRIC LOGGING OF BOREWELL DRILLED AT SITE VILLLAGE BHASUDA, BLOCK BISALPUR, DISRICT PILIBHIT, UTTAR PRADESH UNDER JAL JEEVAN MISSION

Introduction:

The borehole at the site was drilled to a depth of 130.00 meters, and the electric logging was conducted up to 130.00-meter depth using a continuous logger on Sep 30, 2023. The purpose of this logging was to assess the various subsurface strata and properties encountered during drilling, with a focus on resistivity measurements (LON -64" and SHN-16) and self-potential (SP) data. This report provides an analysis of the interpreted data and offers recommendations for further actions under the Jal Jeevan Mission.

LOGGING DATA

Name of agency	Vishwaraj Environment Pvt. Ltd , Atal power Infra
Location	Bhasuda
Block	Bisalpur
District	Pilibhit, U.P
Depth drilled (mbgl)	130
Depth logged (mbgl)	130
Water level (m)	5
LON -64" Resistivty (N-64)	Ohm.m (Blue)
SHN-16 Resistivity (N-16)	Ohm.m (Red)
Self-Potential (SP)	Mv (Green)

		Log Re	port of Bhasuda, I	block Bisalpur, dis	strict Pilibhit , Uttar Pradesl	1		
Sr. No	1	Range n)	Zone Thickness(m)	LON -64" N Resistivity (ohm.m)	Probable Strata	Expected water Qualit		
	From	То						
1	0.00	6.00	6.00	25	Top soil	-		
2	6.00	18.00	12.00	49	Medium Sand	-		
3	18.00	21.50	3.50	22	Clay	-		
4	21.50	39.00	17.50	69	Coarse Sand	-		
5	39.00	43.00	4.00	29	Clay	-		
6	43.00	50.00	7.00	78	Coarse Sand , Gravel	-		
7	50.00	54.50	4.50	37	Clay	-		
8	54.50	57.00	2.50	49	Medium Sand	Good		
9	57.00	59.00	2.00	29	Clay	-		
10	59.00	68.50	9.50	70	Coarse Sand	Good		
11	68.50	78.00	9.50	22	Clay	•		
12	78.00	82.00	4.00	67	Coarse Sand	Good		
13	82.00	86.00	4.00	33	Clay	-		
14	86.00	90.00	4.00	45	Medium Sand	Good		

Regd. Office: 7-A Shanti Nagar , Rajpura Sirhind Bye Pass Road, Near St. Xavier's School

GSTIN. 03BNPPS2540N1ZK



M/S E.R. TECHNOLOGIES

(Govt. Contractor of PH & Civil Works & Electrical Works)

(Specialist in: Deep Tube well, Sick Tube well, Geological and Hydro-Geological Survey, Electric Logging of Borehole, Videography of Borehole, Water Sample & Soil Testing etc.

Ref	Dated1/10/2023
-----	----------------

Log Report of Bhasuda, block Bisalpur, district Pilibhit, Uttar Pradesh

15	90.00	91.50	1.50	25	Clay	-
16	91.50	94.50	3.00	58	Medium Coarse Sand	Good
17	94.50	96.00	1.50	29	Clay	-
18	96.00	98.00	2.00	49	Medium Sand	Good
19	98.00	101.00	3.00	29	clay	-
20	101.00	105.50	4.50	55	Medium Coarse Sand	Good
21	105.50	109.50	4.00	37	Clay	-
22	109.50	114.00	4.50	75	Coarse Sand	Good
23	114.00	116.50	2.50	29	Clay	-
24	116.50	120.50	4.00	56	Medium Coarse Sand	Good
25	120.50	124.00	3.50	29	Clay	5 -
26	124.00	127.50	3.50	47	Medium Sand	Good
27	127.50	130.00	2.50	30	Clay	-

Recommendations:

Based on the interpreted strata data from the electric logging, the following recommendations are provided:

1. Screen Installation:

It is recommended to install screens against the **bold-marked strata** indicated in the interpretation above. These screens will help facilitate water inflow from the identified permeable zones.

2. Expected Water Quality:


The expected water quality in the zones marked as "Good" is anticipated to be favorable.

3. Tubewell Development:

To optimize water yield, it is advised to develop the tubewell using a high-capacity air compressor.

PARKASH KUMAR MSc (Hons)Geology

Regd. Office: 7-A Shanti Nagar , Rajpura Sirhind Bye Pass Road, Near St. Xavier's School



19.