

GROUND WATER INVESTIGATION CENTRE

(Ground Water Assessment & Allied Services) 9/43. Sector 0. 9/43, Sector-9, Jankipuram Extension, Lucknow - 226031

Mob: 9450659011, 8840756551, 9450364183 Email : <u>si.amaresh11@gmail.com</u>, <u>gicaksingh@gmail.com</u> GSITN: 09ANAPS3037Q1ZG

Ref: GIC/JJM/ Shravasti/120

Date : 13.07.23

GEOPHYSICAL BOREHOLE ELECTRICAL LOGGING REPORT

: Village – Rajapur Birpur Zone 1, Block – Hariharpur Rani Site's Location District - Shravasti

: 170 mbgl as Reported by Driller **Drilling Depth**

Logged Depth : 165 mbgl

Date of Logging : 13.07.23

: S.P. & Resistivity (Normal & Lateral) **Types of Log**

Logger Used : Uptron

Details of major aquifer formations explored from interpretation of Geophysical Logs are given below.

SI.	Depth Range	Thickness	Probable Lithology	Remarks	$R_{mf\&}R_{w}$
No.	(m , b gl)	(m)			
1	30 - 37	7	Fine to medium sand	Good	$R_{mf=27.6 \Omega m}$
2	47 - 50	3	Fine to medium sand	Good	$R_{w=29.1 \Omega m}$
3	64 - 71	7	Fine to medium sand	Good	
4	87 - 94	7	Fine to medium sand	Good	1
5	103 - 110	7	Fine to medium sand	Good	1
6	120 - 125	5	Fine to medium sand	Good	1
7	128 - 133	5	Fine to medium sand	Good	
8	139 - 144	5	Fine to medium sand	Good	

Remark: . Almost all zones are intermixed with fine bands of kankar.

CC: Executive Engineer (E/M Div.) U P Jal Nigam (Gramin) Gonda

1 5 V //

