GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-2483

Date: - 04-01-2024

NAME OF SITE

Gram Panchayat- Sujatganj Pastor

BLOCK- Sahaswan

DISTT- Badaun

NAME OF AGENCY

M/s PNC-SPML-JV Badaun



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Conduttancy
Agray

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- SUJATGANJ PASTOR, BLOCK- SAHASWAN, DISTT- BADAUN UNDER JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 140 mtrs. depth. and Logged depth 140 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 04.Jan.2024.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 11	6	Clay kankar	
3.	11 - 30	19	Fine to Medium sand	Medium
4.	30 - 51	21	Clay kankar	
5.	51 - 57*	7.0.2.000000000000000000000000000000000	Medium sand	Medium
6.	57 - 65	8	Clay kankar	
7.	65 - 76*	11	Medium sand	Medium
8.	76 - 81	5	Clay kankar	
9.	81 - 89*	8	Medium sand	Medium
10.	89 - 110	21	Clay kankar	
11.	110 - 125*	15	Medium sand	Medium
12.	125 - 140	15	Clay kankar	

Ground Water Survey Consultancy

Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geologist

GROUND WATER SURVEY CONSULTANCY - AGRAINDIA Longsing GD Supergrand
Faith Standard
Conflict Standard
Conflict Standard
Conflict
C DMAPA 2 0 IGIS/S/04/21-22 XXX E E E E E ¥ Rho a m V Ohm m Ş Ş 8 8 è 8 8 8 8 φŞ 8 ¥ ş 8 8 8 **3**-**3**-8ta-8-В., 8-8-8-8-8-Si-Depth(m) ਰ Ŋ. 8 88-8 37-8 ₫ä. Ø-G-쁑-5-8-13