REPORT ON GEO-PHYSICAL ELECTRICAL LOGGING OF BOREHOLE

at Village: Gandhu Nagla Simbhawali, Hapur, Uttar Pradesh

For State Water Sanitation Mission (Jal Jeevan Mission) UP Jal Nigam(Rural), Hapur, U.P

Submitted Through
M/s. L.C.Infra Projects Private Limited



GLOBAL GROUND WATER CONSULTANTS

(Consulting Geologists & Geophysicists)
84- III Floor, Humayun pur, Safdarjung Enclave, New Delhi - 110 029
Phone: 9818-888824; 9818-007038.

Date: 7th November, 2022

REPORT ON GEO-PHYSICAL RESISTIVITY LOGGING OF BOREHOLE

At

Village: Gandhu Nagla Simbhawali, Hapur, Uttar Pradesh

Introduction:

A deep borehole 145m (475 Feet) was drilled by working agency *M/s*. *L.C.Infra Projects Private Limited, Ghaziabad, U.P,* as a part of their scope of work of development of tubewell under Jal Jeevan Mission Project of SWSM, GGWC conducted a Geophysical Resistivity logging in the above borehole using IGIS's Logger dated on 7th November, 2022

Based on the interpretation of the Logging, the following litho logy has been inferred which tallies fairly well with the well-site litho-log based on mudwash samples.

Depth in m			Expected Litholog	Expected Quality
0	-	3	Surface Soil	
3	-	15	Sandy clay	
15	-	43*	Medium sand	Good
43	-	63	Clay	
63	-	110*	Medium to coarse sand	Good
110) _	128*	Medium sand	Good
128	-	138	Sandy clay	
138	-	145	Clay with kankar	

Conclusions and Recommendations:

- 1. The litholog inferred broadly tallies with that of the well-site litholog.
- 2. The zones marked with asterisk (*) appear to be Aquifer Zones for possible development of tubewell.
- 3. As per thickness of the Aquifer the expected discharge is 80,000 LPH to 90,000 LPH.
- 4. Water Level is 11 m below ground level.
- 5. The Quality of water is Good. However, it is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. The shallow aquifers are also recommended for development to get good quantity of water.
- 7. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.


for Global Groundwater Consultants

(M. RAVI KANTH)

Cround Water Consultation Date:

M.Ravi Kanth

Hydrogeologist



Global Groundwater Consultants Consulting Geologists and Geophysists




Photo of the Site at the time of Logging