



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

Contract: m/s. wells pom

Pumps & EM

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 16/4/2022

Village : ASCHARPUR

Block : KHURZA

District : BULANDSAHAR

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Surface soil	
3-11	Sandy clay	
11-19 [⊗]	Fine sand	Good
19-23	Sandy clay	
23-35 [⊗]	Very Fine sand	Good
35-47 [⊗]	medium sand	Good
47-70	clay kankar	
70-72 [⊗]	Fine sand	Good
72-82	clay	
82-90 [⊗]	Fine sand	Good
90-96 [⊗]	Fine to very fine sand	Good
96-104	clay	
104-106 [⊗]	Very fine sand	Good
106-150	clay kankar	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL :1.0..... METRES

M. RAVI KANTH
16/4/2022