



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srkanthchukka.c23@gamil.com, ravikanth44@yahoo.com

Contract : M.21 kender prabha

SE: Ankit

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Dhan

Tubewell No. :

Date : 04.06.2022

Village : CHANDROLI

Block : Puarakha

District : Saharanpuri

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Surfice soil	
3-7	clay	
7-15	Fine sand	
15-23 [⊗]	Fine sand	good
23-35 [⊗]	medium sand	good
35-40	clay	
40-65 [⊗]	Coarse sand	good
65-68 [⊗]	Fine sand	good
68-78	clay	
78-83 [⊗]	medium sand	good
83-90 [⊗]	Fine sand	good
90-101 [⊗]	medium sand	good
101-106	clay	
106-116 [⊗]	medium sand	good
116-118 [⊗]	Fine sand	good
118-138 [⊗]	medium sand	good
138-144	Fine sand	good
144-151	clay	
151-162 [⊗]	Fine sand	good
162-165	clay kankar.	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL :15..... METRES

M. Ravikanth
M. RAVIKANTH
04/6/2022

Consulting Geologists, Geophysists & Ground Water Specialists

(Hydrogeologist)



Scanned with OKEN Scanner