



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
 Mobile : 9818 888 824, 9818 007 038
 E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

Am. Chinnappa

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 02/05/2022

Village : KASBA DHADDU

Block : PAHASU

District : Buland Shahr, U.P.

Depth in Metres	Expected Litholog	Expected Water Quality
0-3	Surface Soil	
3-6	Medium Sand	
6-33 [⊕]	Medium Sand	Good
33-47 [⊕]	Medium to fine Sand	Good
47-53 [⊕]	Medium Sand	Good
53-57 [⊕]	Fine Sand	Good
57-84 [⊕]	Medium Sand	Good
84-89	clay	
89-94 [⊕]	Fine Sand	Good
94-111	clay	
111-115 [⊕]	Fine Sand	
113-124	clay	
124-135 [⊕]	Fine Sand Brown	
135-150	clay	

For Global Groundwater Consultants

to cite (SRIKANTH)

⊕ EXPECTED WATER ZONE

▼ WATER LEVEL :6 METRES

Consulting Geologists, Geophysicists & Ground Water Specialists

