



contract: ms.welsa.pun



GLOBAL GROUND WATER CONSULTANTS m.kusouaa

84-III Floor, Humayunpur, Sardarjung Enclave, New Delhi - 110 029
 Mobile : 9818 885 824, 9818 007 038
 E-mail : erikanthchukka_c23@gamil.com, ravikanth44@yahoo.com

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 7.06.2022

Village : **Raghu Nathpur**

Block : **UNCHA GAON**

District : **Bulandshahr, U.P**

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Surface Soil	
3-12	Fine sand	
12-30	medium to fine sand	good
30-38	clay	
38-66	medium sand	good
66-74	clay	
74-99	medium sand	good
99-114	Fine sand	good
114-125	medium sand	good
125-150	Fine sand	good

For Global Groundwater Consultants

⊕ EXPECTED WATER ZONE
 ▼ WATER LEVEL : 17 METRES

G. Kant
 M. RAJ KANTH
 7/6/2022
 (Hydrogeologist)