



Contract No: m/s. welspm



**GLOBAL GROUND WATER CONSULTANTS**

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029  
 Mobile : 9818 888 824, 9818 007 038  
 E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

Kusuma

**GEOPHYSICAL ELECTRICAL LOGGING REPORT AT**

Tubewell No. : .....

Date : ..18.09.2022

Village : **THANA GAJROLA**

Block : **UNCHA GAON**

District : **BULANDSHAHAR, U.P**

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Surface Soil	
3-14	medium sand	Good
14-19	Fine Sand	
19-41	medium sand	Good
41-48	Fine sand	Good
48-55	medium sand	Good
55-58	Fine sand	Good
58-67	medium sand	Good
67-70	Fine sand	Good
70-108	medium sand	Good
108-111	Fine sand	Good
111-121	medium sand	Good
121-128	Sandy	
128-132	clay	
132-141	Sandy clay	
141-145	clay	
145-150	medium sand	Good

For Global Groundwater Consultants

*(Signature)*  
 M. RAJ KANTH  
 18/9/2022

⊕ EXPECTED WATER ZONE  
 ▼ WATER LEVEL : .....1.8..... METRES

Consulting Geologists, Geophysicists & Ground Water Specialists.