



**GLOBAL GROUND WATER CONSULTANTS**

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029  
 Mobile : 9818 888 824, 9818 007 038  
 E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

Contractor: M/S. Wells per

SE: M. Rohit Kumar

**GEOPHYSICAL ELECTRICAL LOGGING REPORT AT**

Tubewell No. : .....

Date : 3/10/2022

Village : ROHINDA

Block : KHUTZA

District : GULAND SAHAR, U.P.

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Surficial soil	
3 - 8	Sandy clay	
8 - 19	Fine sand	Good
19 - 23	clay	
23 - 42	medium sand	Good
42 - 62	clay kankar	
62 - 75	Fine sand	Good
75 - 84	clay	
84 - 100	medium sand	Good
100 - 107	clay.	
107 - 110	Very fine sand.	Good
110 - 112	Sandy clay.	
112 - 119	Very fine sand.	Good
119 - 138	clay.	
138 - 155	medium to fine sand	Good
155 - 164	clay kankar.	
164 - 169	Sandy clay.	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL : .....14..... METRES

*(Signature)*  
 M. Rohit Kumar  
 3/10/2022

Consulting Geologists, Geophysicists & Ground Water Specialists

Scanned by CamScanner