

## **SURYA BOREWELL & TRADERS**

Address - Sikandra, Kanpur Dehat

Ref No: - 13-01-13/ SURYA/2024

Date: 13 Jan 2024

## **GEOPHYSICAL WELL LOGGING REPORT**

## **General Description (As reported)**

**Site Location** 

: Vill - Shri Nagar Parsawa Block - Haraiya Satghrw1

District

: Balrampur

**Drilled Depth** 

: 271 m bgl

Borehole drilled by

: Dara Eco Protection (JV) Balrampur.

**Logged Depth** 

: 271 m bgl

**Date of Logging** 

: 12 Jan 2024, 12:31 hrs

Rm & Rsw

: 16.3 Ω-m & 18.40 Ω-m

Lat. & Long.

: 27.671829 & 82.155423.

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below -

S.No	<b>Depth Range</b> (in meter below ground level)		Thickness	<b>Remark</b> (Quality of formation water)
	From	To	(in meter)	(as appear)
1.	41	47	6	Good
2.	50	53	3	Good
3.	56	59	3	Good
4.	66	69	3	Good
5.	74	83	9	Good
6.	97	100	3	Good
7.	105	108	3	Good
8.	118	122 -	4	Good
9.	136	145 -	9	Good
10.	165	171	6	Good
11.	190	194	4	Good
12.	203	208 7	5	Good
13.	221	230	9	Good
14.	249	261	12	Good

Note: - The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine.
- 3. Quality of formation water up to logging depth is Good.
- 4. Log data Attached.

Geophysical Log Interpreted by

Popular

(Rajeev Kumar)

**Geophysicist**M. Sc (Tech) Geophysics

alford

Seen Sw