



Contract: m/s. welspun



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
 Mobile : 9818 888 824, 9818 007 038
 E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

Ms. Arav Simha

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 2.12.2022

Village : Govindpur Dugau Gashora

Block : Anup Sahar

District : Boland Sahar, U.P

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Subsue Soil	
3-11	Fine Sand	
11-24 [⊗]	medium Sand	Good
24-27	clay	
27-64 [⊗]	medium Sand	Good
64-73	clay	
73-81 [⊗]	medium to fine sand	Good
81-92	clay	
92-104 [⊗]	Fine sand	Good
104-110	clay	
110-142 [⊗]	medium Sand	Good
142-150	clay	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE
 ▼ WATER LEVEL : METRES

M. Ravikanth
 M. RAVIKANTH
 2/12/2022

Consulting Geologists, Geophysists & Ground Water Specialists