



Medini

GSTIN : 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 07-02(ii)/JJM/Logging/2022-23

Dated : 08-02-2023

GEOPHYSICAL WELL LOGGING REPORT

Village : Kishni
Block : Sukul Bazar
District : Amethi
Date of Logging : Feb. 07, 2023
Logged Depth : ~~152~~ mbgl.
Borehole Drilled By : Vindhya Telelinks – Gaja Engineering PVT. Ltd. (J.V.)
Drilled Depth : 170 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	17	27	10	Good
2	36	41	05	Good
3	48	51	03	Good
4	61	67	06	Good
5	82	84	02	Moderate

Note :-

Above mentioned E.Logs/parameters reveals:-

- ~~i.~~ Above mentioned groups contains fine sediments.
- ii. Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.
- ~~iii.~~ Below 88 mts. to logged depth i.e. 164 mbgl. borehole contain deteriorated/saline quality of formation water.

For Shri Medini

R.K. BAJPAI
(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.

Verified as per logs provided

Note - Srt No 2 and 3 are highly kankar intermixed.

GSh
08/02/23

