



# GLOBAL GROUND WATER CONSULTANTS

m/s. kcsu

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

## GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. : .....

Date : ..20.08.2022

Village : SAMLI

Block : ANOTA

District : Buland Sahar, U.P

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Surface soil	
3 - 12	Sandy clay	
12 - 19	Fine sand	
19 - 28	Sandy clay	
28 - 56 <sup>⊗</sup>	medium sand	Good
56 - 61	clay	
61 - 66 <sup>⊗</sup>	medium sand	Good
66 - 85	Sandy clay	
85 - 100 <sup>⊗</sup>	medium sand	Good
100 - 106 <sup>⊗</sup>	medium to fine sand	Good
106 - 116 <sup>⊗</sup>	medium sand	Good
116 - 132	clay	
132 - 138	Sandy clay	
138 - 150	clay	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▽ WATER LEVEL : .....17..... METRES

*R. Kanth*  
M. RAJ KANTH  
20/8/2022