



# GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

## GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. : .....

Date : ...6.7.2022

Village : Butada

Block : SHAMLI

District : SHAMLI, O.P

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Surface soil	
3 - 10	Fine sand	
10 - 18	Sandy clay	
18 - 30	Fine sand	
30 - 38 <sup>⊗</sup>	Fine sand	Good
38 - 53 <sup>⊗</sup>	medium sand	Good
53 - 56	clay	
56 - 63 <sup>⊗</sup>	medium sand	Good
63 - 66	clay	
66 - 80 <sup>⊗</sup>	medium sand	Good
80 - 99	Sandy clay	
99 - 105 <sup>⊗</sup>	medium sand	Good
105 - 108	Sandy clay	
108 - 113 <sup>⊗</sup>	medium sand	Good
113 - 119	Sandy clay	
119 - 126 <sup>⊗</sup>	medium sand	Good
126 - 131	clay	
131 - 161 <sup>⊗</sup>	medium sand	Good
161 - 168	sandy clay	


For Global Groundwater Consultants

EXPECTED WATER ZONE

WATER LEVEL : .....30..... METRES

 M. RAVI RAMKI  
6/7/2022

# Butirada (Reorganisation) Shamla



← 200mm →