GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No- 21-01-25/SURYA/2024

Date- 21 Jan 2024

DETAILS OF SITE

VILLAGE – Dhamachauri BLOCK – Harayasat Gharwa DISTRICT – Balrampur

Borehole Drilled By-Shiva Infra Project Ltd.

Log Report By-Surya Borewell & Traders,
Sikandra, Kanpur Dehat



SURYA BOREWELL & TRADERS

Address - Sikandra, Kanpur Dehat

Ref No: - 21-01-25 SURYA/2024

Date: 21 Jan 2024

GEOPHYSICAL WELL LOGGING REPORT

General Description (As reported)

Dhoma chaun

Site Location

: Vill - Devpura Block - Shivpura

District

: Balrampur

Drilled Depth

: 280 m bgl

Borehole drilled by

: Shiva Infra Project Ltd.

Logged Depth

: 280 m bgl

Date of Logging

: 21 Jan 2024, 04:16 hrs

Rm & Rsw

Lat. & Long.

: 16.50 Ω-m : 27.629488 & 17.20 Ω-m & 82.187037.

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below -

S.No	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To	(m meter)	(as appear)
1.	32	38	6	Good
2.	47	52	5	Good
3.	70	88	18	Good
4.	100	103	3	Good
5.	113	119	6	Good
6.	135	144	9	Good
7.	160	164 /	4	Good
8.	173	179 🗸	6	Good
9.	189	198 🗸	9	Good
10.	213	222	9	Good
11.	229	232	3	Good
12.	250	259	9	Good
13.	269	278	9	Good

Note: -The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine.
- 3. Quality of formation water up to logging depth is Good

Sen Sw

4. Log data Attached.

5.

Geophysical Log Interpreted by

(Rajeev Kumar)

Geophysicist

Rejection

M. Sc (Tech) Geophysics



SURYA BOREWELL & TRADERS

Address – Sikandra, Kanpur Dehat

