SURYA BORWELL & TRADERS

Address- Mahmudpur Buzurg, Sikandra, kanpur Dehat

Ref.: 14-12-01 /SURYA/2023-24

Date: 01.12.2023

GEOPHYSICAL WELL LOGGING REPORT

General Description (as reported)

Village

ITWA

Block

HARRAIYA SATGHARWA

District

BALARAMPUR

Borehole Drilled By

DARA-ECO PROTECTION (JV) BALRAMPUR

Drilled Depth

275 mts. (as reported)

Borehole Logged By

Surya Borewell & Traders, Kanpur Dehat

Logged Depth

264 mbgl.

Date of Logging

01,DEC., 2023; 12:00

Rm

18.9 Ω -m

Rsw

14.5 Ω-m

Based on interpretation of presented geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones are as mentioned below -

| S. no. | Depth Range (in meter below ground level) | | Thickness (in meter) | Remark (Quality of formation water) |
|--------|---|-------|-------------------------|-------------------------------------|
| | From | То | | (as appear) |
| 1 | 20 | 30 | 10 | Good |
| 2 | 52 | 58 | 06 | Good |
| 3 | 70 | 90 | 20 | Good |
| 4 | 93 | 110 - | 17 | Good |
| 5 | 111 | 122 - | 11 | Good |
| 6 | 139 | 148 - | 09 | Good |
| 7 | 149 | 156 | 07 | Good |
| 8 | 157 | 162 | 05 | Good |
| 9 | 163 | 178 | 15 | Good |
| 10 | 193 | 201 | 08 | Good |
| 11 | 202 | 210 | 08 | Good |
| 12 | 219 | 229 | 10 | Good |
| 13 | 230 | 243 | 13 | Good |
| 14 | 244 | 258 | 14 | Good |

Note:-

The interpretation of mentioned geophysical logs reveals that -

- 1. The granular zones contain fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either mixed with clay & kanker or very fine sediments.

Presented E.Log Interpreted by

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,

Retired from Irrigation Department, Uttar Pradesh

DIVISION OFFICE (E/M)

U.P. JAL NIGAM RURAL GÓNEZ

ASSISTANT ENGINEER
DIVISION OFFICE (EM)
J.P. JAL NIGAM RURAL GONDA

WW.