SURYA BORWELL & TRADERS

Address- Mahmudpur Buzurg, Sikandra, kanpur Dehat

Ref.: 09-11-27 /SURYA/2023-24 Date: 27.11.2023

GEOPHYSICAL WELL LOGGING REPORT

General Description (as reported)

Village : TRILOKPUR
Block : GANSARI
District : BALRAMPUR

Borehole Drilled By : DARA-ECO PROTECTION (JV) BALRAMPUR

Drilled Depth : 275 mts. (as reported)

Borehole Logged By : Surya Borewell & Traders, Kanpur Dehat

Logged Depth : 272 mbgl.

Date of Logging : November 27, 2023; 10:20

 $\begin{array}{ccccc} Rm & : & 11.9 \ \Omega\text{-m} \\ Rsw & : & 12.2 \ \Omega\text{-m} \end{array}$

Based on interpretation of presented geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones are as mentioned below -

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To	(III IIIetel)	(as appear)
1	20	40	20	Good
2	50	70	20	Good
3	71	90	19	Good
4	90	100	09	Good
5	130	151	21	Good
6	152	180	28	Good
7	181	198	17	Good
8	199	221	22	Good
9	230	240	10	Good
10	241	250	09	Good

Note:-

The interpretation of mentioned geophysical logs reveals that -

- 1. The granular zones contain fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either mixed with clay & kanker or very fine sediments.

Presented E.Log Interpreted by

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant, Retired from Irrigation Department, Uttar Pradesh

