## GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No- 22-12-18 /SURYA/2023

Date- 22 Dec 2023

DETAILS OF SITE VILLAGE – CHAWAI BUJURG BLOCK – SHRIDATTGANJ DISTRICT – BALRAMPUR

NATER

**Borehole Drilled By-**

DARA-ECO PROTACTION (JV) BALRAMPUR

Log Report By-

Surya Borewell & Traders, Sikandra, Kanpur Dehat



Address – Sikandra, Kanpur Dehat

Ref No: - 22-12-18 SURYA/2023

Date: 18 Dec 2023

## **GEOPHYSICAL WELL LOGGING REPORT**

## General Description (As reported)

Site Location	: Vill – CHAWAI BUJURG, Block – SHRIDATTGANJ		
District	: BALRAMPUR		
Drilled Depth	: 165 mts		
Borehole drilled by	: DARA – ECO PROTATION (Jv) BALRAMPUR		
Logged Depth	: 151 mbgl		
Date of Logging	: 18 Dec 2023, 09:37 hrs		
Rm	: 18.2 Ω-m		
Rsw	: 19.8 Ω-m		

Based on interpretation of presented geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below –

Ser No	Depth F (in meter below From		Thickness (in meter)	<b>Remark</b> (Quality of formation water) (as appear)
1	20	38	18	Good
2	47	60	13	Good
3	61	69	08	Good
4	70	79	24	Good
5	88	103	11	Good
6	121	128	07	Good
7	129	136	07	Good

## <u>Note: -</u>

The interpretation of mentioned geophysical logs reveals that-

- 1. The granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine.

Presented E Log Interpreted by

(R. K. Bajpai)



RADER

Address – Sikandra, Kanpur Dehat

