



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
Mobile : 9818 888 824, 9818 007 038
E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

M/s. Shyam
Mr. Rana/Chamarda

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Date : 6/4/2023

Tubewell No. :

Village : Mohammadpur Kehri

Block : Sikandrabad

District : Bulandshahar, U.P.

Depth in Metres	Expected Litholog	Expected Water Quality
0-3	Surface soil	
3-9	Fine sand	
9-21 [⊗]	medium to fine sand	Good
21-27	clay	
27-36 [⊗]	Medium sand	Good
36-43	Sandy clay	
43-54 [⊗]	Medium sand	Good
54-69	clay	
69-83	Sandy clay	
83-86 [⊗]	medium sand	Good
86-98	clay	
98-103	Sandy clay	
103-110 [⊗]	Medium sand	Good
110-126	clay	
126-133 [⊗]	Medium to fine sand	Good
133-150	clay	



EXPECTED WATER ZONE



WATER LEVEL : 10. METRES

For Global Groundwater Consultants

(SRIKANTH)

Consulting Geologists, Geophysists & Ground Water Specialists