GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-461

Date:- 10-05-2023

NAME OF SITE

GRAM PANCHAYAT- Bhitera

BLOCK-Bilsanda

DISTT-Pilibhit

NAME OF AGENCY

M/s Vishvaraj Environment Pvt. Ltd.



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy
Agra

1714

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- BHITERA, BLOCK- BILSANDA, DISTT.- PILIBHIT UNDER JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 150 mtrs. depth. and Logged depth 150 mtrs. at above site. Was drilled by M/s Vishvaraj Environment Pvt. Ltd.

On the request of M/s Vishvaraj Environment Pvt. Ltd. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 10.May.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth	Thickness(m)	Lithology	Expected
	range(m)			Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 18	13	Medium sand	
3.	18 - 30	12	Clay kankar	
4.	30 - 41	11	Medium sand	Med to Good
5.	41 - 46	5	Clay kankar	
6.	46 - 69*	23	Medium sand	Med to Good
7.	69 - 95	26	Clay kankar	
8.	95 - 102*	7	Medium sand	Med to Good
9.	102 - 107	5	Clay kankar	
10.	107 - 121*	14	Medium sand	Med to Good
11.	121 - 134	13	Clay kankar	
12.	134 - 140*	6	Medium sand	Med to Good
13.	140 - 150	10	Fine sand	Med to Good

Ground Water Survey Consultancy

Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium to Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

GROUND WATER SURVEY CONSULTANCY AGRA, UP, India Liggraph Designation
Ligraph Designation
Ligraph Designation
Ligraph Control
L Logger Model: Logger S No. DMPL-2 IGIS/S/01/21-22 ogger Owned by: N 16500 & X A Ohm m 8 ş ខ្ ş ģ 4 4 6 6 6 6 6 ş 岁 ţ 20þ 0w**ö**-5-8-2 Month 짱-1000 N 8--8 **&**-8-5-8-₹ ₩. 8-8-75 80 Depth(m) 8-**>** 8-8-Transport In 8-ន =-ੜ-20-125 ᇴ-3 중-145 150 F

