



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
Mobile : 9818 888 824, 9818 007 038
E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

company: m/s. welspun

m/s. Shivam

Page-3

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 22.05.2023

Village : Chinnasa - Janardar

Block : Buland Sahar

District : Buland Sahar

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Surface Soil	
3 - 14	Fine Sand	
14 - 18	medium sand	good
18 - 25	Fine sand	good
25 - 42	medium sand	good
42 - 45	Sandy clay	
45 - 53	medium sand	good
53 - 58	clay	
58 - 67	medium sand	good
67 - 76	Sandy clay	
76 - 113	medium sand	good
113 - 120	Sandy clay	
120 - 132	clay tanka	
132 - 138	Fine sand	good
138 - 141	clay tanka	

For Global Groundwater Consultant

(Signature)
M. RAVI KANTH
22/5/23

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL :14..... METRES

Consulting Geologists, Geophysists & Ground Water Specialists