



Contract: m/s. Power mech



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

M/s. Shivam

Form-3

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 14/4/2023

Village : RITOLI

Block : SIKANDRABAD

District : BULAND SAHAR, U.P

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Surface Soil	
3 - 10	Sandy clay	
10 - 17	Fine sand	Good
17 - 22	clay	
22 - 55	medium sand	Good
55 - 63	Sandy clay	
63 - 69	medium sand	Good
69 - 78	clay	
78 - 85	medium sand	Good
85 - 101	clay	
101 - 106	Fine sand	Good
106 - 114	Sandy clay	
114 - 120	Very fine sand	Good
120 - 124	Sandy clay	
124 - 128	Very fine sand	Good
128 - 142	clay	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL : METRES

(Signature)
M. RAJ KANTH
14/4/2023

Consulting Geologists, Geophysists & Ground Water Specialists