



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
Mobile : 9818 888 824, 9818 007 038
E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

m/s. welspun

Mr. Parag Pathan

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : *5.8.2023*

Village : **Saidpur Khurampur**

Block : **GULAOATHI**

District : **BULAND SAHAR, U.P**

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	<i>Surface Soil</i>	
3-12	<i>Fine Sand</i>	
12-36	<i>medium sand</i>	<i>Good</i>
36-40	<i>sandy clay</i>	
40-44	<i>medium sand</i>	<i>Good</i>
44-48	<i>sandy clay</i>	
48-80	<i>medium sand</i>	<i>Good</i>
80-90	<i>clay</i>	
90-127	<i>medium sand</i>	<i>Good</i>
127-137	<i>sandy clay</i>	
137-150	<i>clay</i>	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL : *12* METRES

Filters

Signature
M. RAJIKANTH
5/8/2023

Consulting Geologists, Geophysists & Ground Water Specialists