FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Mob: - 8744928231

Date:31-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Mishrauliya, BlockGasari, District Balrampur, U.P.

Name of Village : Mishrauliya Block — Gasari

District: Balrampur

Date : 31-10-2023 Depth logged : 264.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То	` ′	
1	6	12	6	Sandy Clay
2	12	50	38	Fine to medium Sand
4	50	58	8	Clay and kankar
5	58	82	24	Fine sand
6	82	90	8	Clay and kankar
7	90	96	6	Fine sand
8	96	102	6	Clay and kankar
9	102	106	4	Fine sand
10	106	110	4	Clay and kankar
11	110	120	10	Fine sand
12	120	128	8	Clay and kankar
13	128	136	8	Fine sand
14	136	150	14	Clay and kankar
15	150	158	8	Fine sand
16	158	163	5	Clay and kankar
17	163	172	9	Fine sand
18	172	182	10	sandy clay
19	182	186	4	Fine sand
20	186	200	14	Clay and kankar
21	200	210	10	Fine sand
22	210	214	4	Clay and kankar
23	214	232	18	Fine sand

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
24	232	246	14	Clay and kankar
25	246	252	6	Fine sand
26	252	258	6	Clay and kankar
27	258	264	6	Fine sand

For First Best Solution

Authorized Signatory