# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## **GEO-PHYSICAL WELL ELECTOLOGGING REPORT**

Ref No:-A-118

Date:- 07-04-2023

#### NAME OF SITE

GRAM PANCHAYAT- Khiriya BLOCK- Nigohi

DISTT- Shahjahanpur

#### NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



# GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

> Ground Water onsultancy

# REPORT ON GEOPHYSICAL WELL LOGGING AT

# GRAM PANCHAYAT- KHIRIYA, BLOCK- NIGOHI, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION


#### Introduction:

A Deep bore hole was drilled 125 mtrs. depth. and Logged depth 125 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 07.April.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m	Lithology	Expected Water Quality		
1.	0 - 5	5	Surface soil			
2.	5 - 10	5	Clay	5		
3.	10 - 15	5	Fine sand	1		
4.	15 - 22	7	Clay kankar	1 1" = 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
5.	22 - 27	5	Fine to Medium sand	Med to Good		
6.	27 - 45	18	Clay kankar			
7.	45 - 60*	15	Medium sand	Med to Good		
8.	60 - 65	5	Clay kankar	I se		
9.	65 - 75*	10	Fine to Medium sand & kankar	Med to Good		
10.	75 - 80	5	Clay kankar			
11.	80 - 106*	26	Medium sand	Med to Good		
12.	106 - 115	9	Clay kankar			
13.	115 - 125*	10	Medium sand	Med to Good		



### Conclusions and Recommendations:-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium to Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

**Ground Water Survey Consultancy** 

	- AGRA INDIA	GROUND WATER SURVEY	Logger Derred by	DMPL-2	Z SP (m s)		IGS/\$/04/21-22	LOCCOT S Ne		5400 C.m. 40	G App 1013 Value	Vyor Din Startage	Z 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	NIP ON
-10-	; p	ة <del>ب</del>	m V Y Y	49-	\$ \$	<del>7</del> 0	20-	5 1		Ohm r		120-	145	Ş
					Ц,	2	L	,	_					
					\$	_	B	_	7			L		
					5			3	_	7			_	
				<	R.	_	8		2	-		_		L
		$\perp$	Ц	5							-	-		
A CANADA		1	-	1		_		I		<		3	, i	
		-				_		2		$\leq$				1
		_	茸	1			1	>		3	>	<u></u>		
				1				2			=	>	1-	
			1 10	5					D				_	10 A
A TABLES		$\perp$	1		Ш		ļ		[}]			1	_	_
		1			Ш				1			(	-	
		1		1	Ц	The second secon	(	3		<	-			
		$\perp$	4	>	Ц	and the same of th	_	2			3	>_		
			3					1				>		
		-		_	2 2			<	1	-			_	
	E.E.							-	1				<u>{</u>	
			5	1		1.			11		5.		2	_
		-	F	-		-		Ñ.	13		2		3	
		-		+	H	V -1	-	1		-	_	-	3	
		1	H	+	H	-	-		1		_	-	3	_
		4	1	+		-	9	1	_	=		F		_
			2	+	H	J. N.	15	-	-	3	E	-	-	A 1
		3	H	+	H	-	1.7		7	_	14.1	-	2	_
	<		H	-	H		-	1	1	-	-	-	1	_
Ŀ	2/20				A STATE OF THE STA									

