## GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

### GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-778

Date 10-06-2025

#### NAME OF SITE

GRAM PANCHAYAT- Japnapur BLOCK- Bhawalkhera

DISTE-Stubishment

#### NAME OF AGENCY

M's NCC Ltd. Shahjahanpur



#### GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Finozabad Road, Agear 28,2006 (M): 9412260823, 9794625420, 9761163000, Email: grass: agracionables com

ISO : 9001 ; 2015

Greens Water Somer Conductions

## REPORT ON GEOPHYSICAL WELL LOGGING

# GRAM PANCHAYAT- JAPNAPUR, BLOCK- BHAWALKHERA, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 10.June.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral.

Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

| S.No. | Depth<br>range(m) | Thickness(m) | Lithology           | Expected Water<br>Quality |
|-------|-------------------|--------------|---------------------|---------------------------|
| 1     | 0 - 5             | 5            | Surface soil        | "                         |
| 2.    | 5 - 15            | 10           | Fine sand & kankar  |                           |
| 3.    | 15 - 25           | 10           | Clay kankar         |                           |
| 4     | 25 - 33           | 8            | Medium sand         | Medium                    |
| 5.    | 33 - 50           | 17           | Clay kankar         |                           |
| 6.    | 50 - 57*          | 7            | Medium sand         | Medium                    |
| 7.    | 57 - 67           | 10           | Clay kankar         |                           |
| 8.    | 67 - 70*          | 3            | Fine to Medium sand | Medium                    |
| 9.    | 70 - 91           | 21           | Clay kankar         |                           |
| 10.   | 91 - 105*         | 14           | Medium sand         | Medium                    |
| 11.   | 105 - 110         | 5 1 5        | Clay kankar         | 5.1                       |
| 12.   | 110 - 122*        | 12           | Medium sand         | Medium                    |
| 13.   | 122 - 130         | 8            | Clay kankar         |                           |



#### Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

**Ground Water Survey Consultancy** 



