### TROUND WATER SURVEY CONSULTAN

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

#### GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-523

Date:- 16-05-2023

#### NAME OF SITE

a proving the a smaller to the merchant than some a fitting. Their Restrict to the

Dennes es crecis des ses frematiques encep el trutt el purp atrocas hojo pas el Álber

the burks. There is presented from well contactly and property in a following their

GRAM PANCHAYAT- Jashanpur

BLOCK- Kanth

DISTT-Shahjahanpur

#### NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



#### GROUND WATER SURVEY CONSULTANCS

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy Agra

## REPORT ON GEOPHYSICAL WELL LOGGING

# GRAM PANCHAYAT- JASHANPUR, BLOCK- KANTH, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 120 mtrs. depth. and Logged depth 120 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 16.May.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1	5	Surface soil	
1	3	Dry sand	* * 6
1	4	Clay kankar	
	9	Fine sand	Medium
1	9	Clay kankar	
	24	Medium sand & kankar	Medium
		Clay kankar	
		Medium sand	Medium
		Clay kankar	
	ALL PRODUCTION TO THE PRODUCTION OF THE PRODUCTI	Medium sand	Medium
1		Clay kankar	
5	i	Medium sand	Medium
		Clay	
		Medium sand	1 Medium
	range(m)  0 - 5  5 - 8  8 - 12  12 - 21  21 - 30  30 - 54*  54 - 58  58 - 86*  86 - 90  90 - 100*  100 - 102  102 - 113*  113 - 116	range(m)  0 - 5	range(m)  0 - 5

#### Conclusions and Recommendations :-

- The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- The Quality of water is expected Medium.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

**Ground Water Survey Consultancy** 



