# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL **ELECTOLOGGING REPORT**

Ref No:- 1449

Date: - 27-12-2022

### NAME OF SITE

Gram Panchayat- Sahvia Kalan BLOCK- Shahabad

DISTT- Rampur

NAME OF AGENCY

M/s NKG Infrastructure Limited Delhi



# GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO: 9001: 2015

**Ground Water Survey Consultancy** 

# REPORT ON GEOPHYSICAL WELL LOGGING AT

# GRAM PANCHAYAT- SAHVIA KALAN, BLOCK- SHAHABAD, DISTT- RAMPUR UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 140 mtrs. depth. and Logged depth 140 mtrs. at above site. Was drilled by M/s NKG Infrastructure Limited, Delhi.

On the request of M/s NKG Infrastructure Limited, Delhi. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 27.Dec.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral.

Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5	Clay	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3.	10 - 25	15	Fine to Medium sand	Medium
4.	25 - 30	5	Clay kankar	
5.	. 30 - 40	10	Medium sand	Medium
6.	40 - 45	5	Clay kankar	
7.	45 - 72*	. 27	Medium sand	Medium
8.	72 - 75	3	Clay kankar	
9.	75 - 110*	35	Medium sand	Medium
10.	110 - 115	5	Clay kankar	
11.	115 - 121*	6	Medium sand	Medium
12.	121 - 125	4	Kankar	
13.	125 - 140*	15	Medium sand	Medium

**Ground Water Survey Consultancy** 

Agra

# Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

J'AN

**Ground Water Survey Consultancy** 

Ground water Survey
Consultancy - Agra
India 16/5/5/03/21-22 Linguist of Languages from Standard Dem Languages of Linguist of 11 Sec. 2022 15 Sec. 2022 15 Sec. 2022 DIMPL-2 Lager Chines of Logging Details Rho a
Nie isn
Nie isn > SP (m V) th A -153-\*\*\* ទុ 20ŗ 50 8 ģ 8 A Sammary Port 8-T. Jaman 8 - Myselson of the same with the same of th 8 Charles of the 8 33 8 S 8 \$5. 2 8-Mary Mary 8-Depth (m) 8 - June Z. 8 - Total 8-8-2.-중-중-**3**-Z. g-G. g. 5 5-II

