GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL **ELECTOLOGGING REPORT**

JAL ATVAN MISHON

Ref No:-B- 714

Date: - 31-05-2023

A Long berk hise was an and, and Louged appth 130 mire NAME OF SITE

GRAM PANCHAYAT- Rouli Bouri BLOCK- Jalalabad DISTT- Shahjahanpur

in the laborary and the same of the control of the same and the same and the

or Birg a fire the same a from any case to some given in the Salament while

NAME OF AGENCY

Details of man impaled felt (Might applicated from ledging of close belonged fined with the salety

Licardard Purp evidens. Shift Sparanter, Short normal AV 16), can a Rombal AV 541, Lateral

M/s NCC Ltd. Shahjahanpur



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc agra@yahoo.com

> ISO: 9001: 2015 Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- ROULI BOURI, BLOCK- JALALABAD, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

married with any totals to inspice to be aquifer godes for people

Introduction:

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 31.May.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	192
2.	5 - 15	10	Clay kankar	
3.	15 - 23	8	Fine sand	
4.	23 - 32	9	Clay kankar	
5.	32 - 50	18	Medium sand	Good
6.	50 - 53	3	Clay kankar	
7.	53 - 77*	24	Medium sand	Good
8.	77 - 95	18	Clay kankar	
9.	95 - 101*	6	Fine to Medium sand	Good
10.	101 - 105	4	Clay kankar	
11.	105 - 115*	10	Fine to Medium sand	Good
12.	115 - 130	15	Clay kankar	1 =



Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy



DMPL-2 DMPL-2 GROUND WATER SURVEY CONSULTANCY AGRA, UP, INDIA	u u	MINESS NO. 1
20- 20- 0- 0- 10- 10- 10- 15- 20- 25- 20- 25- 20- 25- 20- 25- 20- 25- 20- 25- 26- 26- 26- 26- 26- 26- 26- 26- 26- 26		